

**CITY OF BALTIMORE WET WEATHER CONSENT DECREE
SMOKE AND DYED WATER TESTING FORM**

Page 1 of 4

Sewershed: JONES FALLS

Company: REI/DRAYCO

Date: 07/18/2008

Test to be Performed: SMOKE

Ground Condition: DRY


Supervisor: ER

Manhole ID: S31QQ_028MH

Test ID: 0994-386

Notifications
Made: X
(Residents, Fire, 311)

Field Sketch: (Show All Manholes with Numbers, Blower Placement Location, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photograph Numbers)



Page 2 of 4

Date: 07/18/2008

Supervisor: E.R.

Notifications Made: X
(Residents, Fire, 311)

Test ID: 0994-386

[illegible]

	Source Type	Location	Sector	Severity		Source Type	Location		
01	Main Sewer	Paved Concrete	Public	No Smoke	10	MH Frame Seal	Non-Paved		
02	Service Line	Paved Asphalt	Private	Trace	11	Storm Drain	Field/Woods		
03	Cleanout	Paved Other		Moderate	12	Catch Basin/In	Alley		
04	Downspout	Driveway		Major	13	Storm Manhole	Golf Course		
05	Area Drain	Sidewalk			14	Storm Ditch	Other		
06	Driveway Drain	Curb			15	Excavation			
07	Stairwell Drain	Yard- Front			16	Other			
08	Foundation Drain	Yard-Back							
09	Building Interior	Yard- Side							

CITY OF BALTIMORE
SMOKE TESTING OBSERVATION SUMMARY
JONES FALLS SEWERSHED
BALTIMORE CITY PROJECT 994
REI/DRAYCO

Unique Test ID: 386	Date: 07/18/2008	Basin: JF-19
Defect No: OB01-01	Supervisor: E.R.	Dye Test Recommended: N
Address: 401 W. 26TH ST.		
Source Type: 16	Location: 14	Severity: 03
Sector: 02	Drainage Area: 10	
Comments: SMOKE IS COMING FROM HOLE IN GROUND IN UNPAVED PARKING LOT AT ADDRESS. DEFECT IS ALONG THE NORTHERN FENCE ADJACENT TO MAIN SEWER LINE		

SMOKE TEST PHOTOGRAPHS



Photograph No: OB01-01
Filename: 0994-386_OB01-01.jpg

CITY OF BALTIMORE
SMOKE TESTING OBSERVATION SUMMARY
JONES FALLS SEWERSHED
BALTIMORE CITY PROJECT 994
REI/DRAYCO

Unique Test ID: 386	Date: 07/18/2008	Basin: JF-19
Defect No: OB02-01	Supervisor: E.R.	Dye Test Recommended: N
Address: 401 W. 26TH ST.		
Source Type: 16	Location: 05	Severity: 03
Sector: 01	Drainage Area: 6	
Comments: SMOKE IS COMING FROM WATER METER ACCESS IN FRONT OF ADDRESS ENTRANCE		

SMOKE TEST PHOTOGRAPHS



Photograph No: OB02-01
Filename: 0994-386_OB02-01.jpg